

Unit 2
Physical Quantities
&
Measuring Length

Lesson Objectives

- Show understanding that all physical quantities consist of a numerical magnitude and a unit
- Recall the following base quantities and their units: mass (kg), length (m), time (s), current (A) and temperature (K)
- use the following prefixes and their symbols to indicate decimal sub-multiples and multiples of the SI units: nano (n), micro (μ), milli (m), centi (c), deci (d), kilo (k), mega (M)
- show an understanding of the orders of magnitude of the sizes of common objects ranging from a typical atom to the Earth
- describe how to measure a variety of lengths with appropriate accuracy by means of tapes, rules, micrometers and calipers, using a vernier scale as necessary

1.1 Physical Quantities

- A **physical quantity** is a quantity which can be measured. It is a **number** with a **unit**.
- **Examples of physical quantities are:**
 - **Length**
 - **Volume**
 - **Time**
 - **Temperature**
 - **Mass**

Physical Quantities

Accurate measurement of physical quantities can be done by accurate and universal instruments.

- Length-metre rule
- Volume-measuring cylinder
- Time-electronic stopwatch
- Temperature-thermometer
- Mass-electronic balance

1.2 S.I. Units

- Since 1960, scientists all over the world have agreed to adopt a single system of units
 - **SI Units** (Système International d'Unités)
- An adaptation of the metric system

S.I. Units

Physical quantity	SI unit	Symbol for unit
Length, l	metre	m
Mass, m	kilogram	kg
Time, t	second	s
Temperature, T	kelvin	K
Electric current, I	ampere	A


1.3 Prefixes

- There is a need to use a prefix when the numbers get unusually large or small.

E.g. 1 000 000 m

- So we can convert this value to 1000km, which is shorter to write.


- This will make things more meaningful.



Prefixes

The Use of Prefixes in Our Daily Lives

- Nanotechnology equipments:
 - ✓ Computer circuit boards
 - ✓ Mobile phones
 - ✓ Enhancing car car bumpers.
- Astrology
 - ✓ Travelling in light years



1.3 Prefixes

Prefix	Symbol	Meaning
tera	T	trillion
giga	G	billion
mega	M	million
kilo	k	thousand
hecto	h	hundred
deca	da	ten
deci	d	tenth
centi	c	hundredth
milli	m	thousandth
micro	μ	millionth
nano	n	billionth
pico	p	trillionth

Prefixes

Prefix	Symbol	Value
tera	T	10^{12}
giga	G	10^9
mega	M	10^6
kilo	k	10^3
hecto	h	10^2
deca	da	10
deci	d	10^{-1}
centi	c	10^{-2}
milli	m	10^{-3}
micro	μ	10^{-6}
nano	n	10^{-9}
pico	p	10^{-12}

$$\begin{aligned} 135 \text{ nm} &= 135 \times 10^{-9} \text{ m} \\ 350 \text{ mg} &= 350 \times 10^{-3} \text{ g} \\ 92 \text{ km} &= 92 \times 10^3 \text{ m} \\ 68 \text{ MW} &= 68 \times 10^6 \text{ W} \end{aligned}$$

Complete the table below with the correct symbol/ prefix /factor.

<u><i>Symbol</i></u>	prefix	Factor
M		10^6
	kilo	
c		
	milli	
μ		10^{-6}
	nano	

1.5 Standard form

- Standard form is a way of writing down very large or very small numbers easily.

For example:

i. 1.23×10^6 s

ii. 6.1×10 kg

iii. 5.55×10^{-9} m

What do you observe?

A number in standard form is of the form $A \times 10^n$, where $1 \leq A < 10$ and n is an integer.

How do you perform standard form tricks:

e.g. $1 \times 10 = 10$

$$1.1 \times 10 = 11$$

$$1.1 \times 100 = 110$$

$$1.1 \times 1000 = 1100$$

What trend do you see? (Hint: look at the decimal point)

How do you perform standard form tricks:

e.g. $10 \div 10 = 1$

$$1.1 \div 10 = 0.11$$

$$1.1 \div 100 = 0.011$$

$$1.1 \div 1000 = 0.0011$$

So what is your conclusion?

Try it yourself!


Convert the following into standard form in S.I. units:

135 nm = 1.35 x 10² nm = 1.35 x 10⁻⁷ m

350 mg = _____ mg = _____ g

92 km = _____ km = _____ m

68 MW = _____ MW = _____ W



1.6 Measuring length

The **accuracy** of an instrument is the degree to which the results of readings of an instrument approach the true value of the calculated or measured quantities.

Usually, we take the **accuracy** of an instrument as the smallest division on the scale of the instrument.

Instruments for measuring length:

- Measuring tape
- Metre rule
- Vernier calipers
- Micrometer screw gauge


Measuring length

Accuracy of a measuring tape

→ 0.1cm or 1mm

Accuracy of a ruler

→ 0.1cm or 1mm





Measurement of length

Metre rule:

- For length from several cm to 1 m.
- Accuracy to 0.1 cm or 1 mm
- Precaution: Avoid parallax error

Parallax error:

Error arises due to a relative movement between the scale when an observer's eye is moved from side to side.



Test yourself

Complete the following conversion

$$1 \text{ km} = \underline{\hspace{2cm}} \text{ m} = \underline{\hspace{2cm}} \text{ cm} = \underline{\hspace{2cm}} \text{ mm}$$

$$\underline{\hspace{2cm}} \text{ km} = 1 \text{ m} = \underline{\hspace{2cm}} \text{ cm} = \underline{\hspace{2cm}} \text{ mm}$$

$$\underline{\hspace{2cm}} \text{ km} = \underline{\hspace{2cm}} \text{ m} = 1 \text{ cm} = \underline{\hspace{2cm}} \text{ mm}$$

$$\underline{\hspace{2cm}} \text{ km} = \underline{\hspace{2cm}} \text{ m} = \underline{\hspace{2cm}} \text{ cm} = 1 \text{ mm}$$

Test yourself: Answers

Complete the following conversion


$$1 \text{ km} = \underline{1000} \text{ m} = \underline{100\ 000} \text{ cm} = \underline{1\ 000\ 000} \text{ mm}$$

$$\underline{0.001} \text{ km} = 1 \text{ m} = \underline{100} \text{ cm} = \underline{1000} \text{ mm}$$

$$\underline{0.000\ 01} \text{ km} = \underline{0.01} \text{ m} = 1 \text{ cm} = \underline{10} \text{ mm}$$

$$\underline{0.000\ 001} \text{ km} = \underline{0.001} \text{ m} = \underline{0.1} \text{ cm} = 1 \text{ mm}$$



Vernier Calipers




This instrument measures short **LENGTH** especially suitable for measuring diameters or radii of circular objects.

Accuracy of a vernier calipers is **0.01cm** or **0.1mm**


How to read the Vernier Calipers?




How to read the Vernier Scale?



How to read the Vernier Scale?



How to read the Vernier Scale?




Main scale reading = 0.8cm

Vernier scale reading = 0.05cm

Measured length = $0.8\text{cm} + 0.05\text{cm} = 0.85\text{cm}$

Reading the vernier scale




Main scale reading = 1.4cm

Vernier scale reading = 0.04cm

Measured length = 1.4cm + 0.04cm = 1.44cm

Test yourself!




Main scale reading = 1.4cm

Vernier scale reading = 0.06cm

Measured length = $1.4\text{cm} + 0.06\text{cm} = 1.46\text{cm}$

Test yourself!




Main scale reading = 2.8cm

Vernier scale reading = 0.07cm

Measured length = 2.8cm + 0.07cm = 2.87cm

Test yourself!




Main scale reading = 0.3cm

Vernier scale reading = 0.08cm

Measured length = $0.3\text{cm} + 0.08\text{cm} = 0.38\text{cm}$

Test yourself!




Main scale reading = 1.0cm

Vernier scale reading = 0.00cm

Measured length = 1.0cm + 0.00cm = 1.00cm


Test yourself!

What readings are shown on the following scales?



Main scale: **2.0**
Vernier scale: **0.09**

Reading: 2.09cm




Main scale: **1.1**
Vernier scale: **0.09**


Reading: 1.19 cm

Test yourself!

What readings are shown on the following scales?



Reading: 0.83 cm



Reading: 1.55 cm

<http://members.shaw.ca/ron.blond/Vern.APPLET/>


<http://www.phys.hawaii.edu/%7Eteb/java/ntnujava/ruler/vernier.html>

When a measuring instrument shows a reading when there actually should be none (i.e the reading should be zero), there is an error.

What is this error called?

**Zero
Error**


Zero error: -ve error



$$\text{Zero Error} = \mathbf{0.04\text{cm}}$$

The subsequent readings taken with this instrument is to be decreased by this error.

Zero error-example 1




Observed reading = **0.85cm**

Actual diameter = **0.85 - 0.04 = 0.81cm**

In this example, the zero error is to be reduced from the OBSERVED reading to get the ACTUAL measurement.

Zero error: +ve error




Zero Error = **0.03 cm !!!!!**

NOT 0.07 cm!

The subsequent readings taken with this instrument is to be increased by this error.

Zero error-example 2




Observed reading = **1.44 cm**

Actual length = **1.44 + 0.03 = 1.47 cm**


In this example, the zero error is **ADDED** to the **OBSERVED** reading to get the **ACTUAL** measurement.

Test yourself!

What zero errors are shown on the following scales?




Zero error = 0.04 cm



Zero error = 0.03 cm

1.6 Measuring length

Micrometer screw gauge



This instrument measures very short **LENGTH** especially suitable for measuring diameters or radii of wires.

<http://www.upscale.utoronto.ca/PVB/Harrison/Micrometer/Micrometer.html>



Micrometer screw gauge

- Measure up to 25 mm
- Accuracy to 0.001 cm or 0.01 mm

Precautions:

- Zero error should be noted and corrected.
- The ratchet must be used to avoid over tightening.
- Several readings should be taken and the average value is taken.

How to read the micrometer screw gauge?



Main scale = 3.0 mm
Thim. scale = 0.46 mm
reading = 3.46 mm

The edge of thimble

**E
X
A
M
P
L
E

1**



Main scale reading= 7.5mm

Thimble scale reading= 0.22mm

Measured length= $7.5 + 0.22 = 7.72\text{mm}$

E X A M P L E




2

Main scale reading= 7.0mm

Thimble scale reading= 0.38mm

Measured length= $7.0 + 0.38 = 7.38\text{mm}$

Test yourself



Main scale reading= 3.0mm

Thimble scale reading= 0.46mm

Measured length= $3.0 + 0.46 = 3.46\text{mm}$

Test yourself



Main scale reading= 3.5mm

Thimble scale reading= 0.06mm

Measured length= $3.5 + 0.06 = 3.56\text{mm}$

Test yourself



Main scale reading= 5.5 mm

Thimble scale reading= 0.30mm

Measured length= $5.5 + 0.30 = 5.80\text{mm}$

Micrometer Screw Gauge

- Similar to the usage of the vernier calipers, the micrometer must be checked for **zero error** before the measurement is taken.
- The error is then **added** or **subtracted** from the **observed** reading to get the **actual** reading.

Zero error: -ve error



Zero error
= - 0.06mm

This zero error should be **REDUCED** from the observed reading.

This **-ve** error means reduce the final reading by this amount.

Zero error: +ve error



Zero error


$$= 0.04 \text{ mm}$$

This zero error should be **added** to the observed reading.


This +ve error means to increase the final reading by this amount.

Test yourself


Read the zero errors shown below:



All measurements should be reduced by 0.03 mm (-0.03 mm)



Zero error = 0.00



All measurements should be increased by 0.03 mm (+0.03 mm)